

# *St. Joseph Apache Mission Restoration Project*



*Illustrated Progress Report for May 2010 through October 2010*



The crew working on Choir loft stair case roof.



Roof almost completed.



Trainees David Walters & Sam Sosa working with Martin Pizarro on cornice wall.





Tommy & Martin working on alcove roof



Martin & Sam working on Belfry louvers.



Tommy & Nikona working on bell tower





Tribal Water Department putting in new waterline.

Alfred Torrez learning the ropes from Nikona & Sam on setting up scaffolding.



The crew working on the south interior wall.



Example of a large void in the south interior wall.

